



SGS Canada Inc.

P.O. Box 4300 - 185 Concession St.
Lakefield - Ontario - KOL 2H0
Phone: 705-652-2000 FAX: 705-652-6365

**Not Reportable as per Chain of Custody
Works #: 1156**

Project : PO#017018

27-December-2013

OCWA-Trent Valley (Quinte Mohawk School)

Attn : James Taylor

**Date Rec. : 23 December 2013
LR Report: CA14552-DEC13**

Box 20157, 131 St. Paul St.
Belleville, ON
K8N 5V1,

Copy: #1

Phone: 613-962-5454
Fax:pdf-ID Plant

CERTIFICATE OF ANALYSIS

Final Report

Sample ID	Sample Date & Time	Temperature Upon Receipt °C	Free Chlorine mg/L	Total Coliform cfu/100mL	E. Coli cfu/100mL	Heterotrophic Plate Count (HPC) cfu/1mL
1: Analysis Start Date		---	---	23-Dec-13	23-Dec-13	23-Dec-13
2: Analysis Start Time		---	---	14:30	14:30	14:00
3: Analysis Approval Date		--	--	26-Dec-13	26-Dec-13	26-Dec-13
4: Analysis Approval Time		--	--	12:04	12:04	12:04
5: MAC		--	--	0	0	---
6: 26F9D RW RW-QMS: Raw Water Tap 26F9D RW	23-Dec-13 07:15	8.0	---	0	0	86
7: 6712 NR/DW DW1-QMS Daycare (Fountain Outside) 6712 NR/DW	23-Dec-13 08:07	8.0	0.24	0	0	0
8: 13480 NR/DW DW3-QMS: Fountain Water Girls Bathroom 13480 NR/DW	23-Dec-13 08:13	8.0	1.19	0	0	0

Total and/or Free Residual Chlorine was not analyzed by SGS Environmental Services.


 Carrie Greenlaw
 Project Specialist
 Environmental Services, Analytical