



SGS Canada Inc.

P.O. Box 4300 - 185 Concession St.
Lakefield - Ontario - K0L 2H0
Phone: 705-652-2000 FAX: 705-652-6365

Works #: 1156

Project : PO#017018

02-January-2014

OCWA-Trent Valley (Quinte Mohawk School)

Attn : James Taylor

Date Rec. : 30 December 2013

LR Report: CA14674-DEC13

Box 20157, 131 St. Paul St.
Belleville, ON
K8N 5V1,

Copy: #1

Phone: 613-962-5454
Fax:pdf-ID Plant


CERTIFICATE OF ANALYSIS

Final Report

Sample ID	Sample Date & Time	Temp Upon Receipt °C	ResCl Free mg/L
1: Analysis Start Date		---	---
2: Analysis Start Time		---	---
3: Analysis Approval Date		--	--
4: Analysis Approval Time		--	--
5: MAC		--	--
6: 26F9D RW RW-QMS: Raw Water 26F9D RW	30-Dec-13 07:52	8.0	---
7: 6712 NR DW DW1-QMS Daycare (fountain outside) 6712 NR/DW	30-Dec-13 08:09	8.0	1.08
8: 13481 NR/DW DW3-QMS: Fountain Water Outside Boys Bathroom 13481 NR/DW	30-Dec-13 08:04	8.0	1.41

Sample ID	Total Coliform cfu/100mL	E.Coli cfu/100mL	HPC cfu/1mL
1: Analysis Start Date	30-Dec-13	30-Dec-13	30-Dec-13
2: Analysis Start Time	13:35	13:35	13:20
3: Analysis Approval Date	02-Jan-14	02-Jan-14	02-Jan-14
4: Analysis Approval Time	09:32	09:32	09:32
5: MAC	0	0	---
6: 26F9D RW RW-QMS: Raw Water 26F9D RW	0	0	360
7: 6712 NR DW DW1-QMS Daycare (fountain outside) 6712 NR/DW	0	0	0
8: 13481 NR/DW DW3-QMS: Fountain Water Outside Boys Bathroom 13481 NR/DW	0	0	0

Total and/or Free Residual Chlorine was not analyzed by SGS Environmental Services.
NR - Not reportable under applicable Provincial drinking water regulations as per client.



Kimberley Didsbury
 Project Specialist
 Environmental Services, Analytical