

SGS Canada Inc.

P.O. Box 4300 - 185 Concession St.
Lakefield - Ontario - KOL 2H0
Phone: 705-652-2000 FAX: 705-652-6365

June-06-13

OCWA-Trent Valley (Quinte Mohawk School)

Attn : James Taylor

Date Rec. : 04 June 2013
LR Report: CA16178-JUN13

Box 20157, 131 St. Paul St.
Belleville, ON
K8N 5V1,

Copy: #1

Phone: 613-962-5454
Fax:pdf-ID Plant

CERTIFICATE OF ANALYSIS

Final Report

Sample ID	Sample Date & Time	Temperature Upon Receipt °C	Free Chlorine mg/L	Total Coliform cfu/100mL	E. Coli cfu/100mL	Heterotrophic Plate Count (HPC) cfu/1mL
1: Analysis Start Date		---	---	04-Jun-13	04-Jun-13	04-Jun-13
2: Analysis Start Time		---	---	15:50	15:50	15:25
3: Analysis Approval Date		--	--	06-Jun-13	06-Jun-13	06-Jun-13
4: Analysis Approval Time		--	--	10:55	10:55	14:08
5: MAC		--	--	0	0	---
6: 26F9D RW RW QMS: Raw Water Tap	03-Jun-13 09:37	10.0	---	0	0	9
7: 1EC6A NR/DW DW2 QMS Staff Room Tap	03-Jun-13 10:05	10.0	1.28	0	0	0
8: 6712 NR/DW DW1 QMS Daycare	03-Jun-13 10:15	10.0	1.21	0	0	0

Total and/or Free Residual Chlorine was not analyzed by SGS Environmental Services.



Carrie Greenlaw
Project Specialist
Environmental Services, Analytical