



**SGS Canada Inc.**

P.O. Box 4300 - 185 Concession St.  
Lakefield - Ontario - K0L 2H0  
Phone: 705-652-2000 FAX: 705-652-6365

Not Reportable as per Chain of Custody  
Works #: 1156

Project : PO#017018

07-July-2014

**OCWA-Trent Valley (Quinte Mohawk School)**

Attn : James Taylor

Date Rec. : 03 July 2014

LR Report: CA16195-JUL14

Box 20157, 131 St. Paul St.  
Belleville, ON  
K8N 5V1,

Copy: #1

Phone: 613-962-5454  
Fax:pdf-ID Plant

# CERTIFICATE OF ANALYSIS

## Final Report

Sample ID	Sample Date & Time	Temperature Upon Receipt °C	Free Chlorine mg/L	Total Coliform cfu/100mL	E. Coli cfu/100mL	Heterotrophic Plate Count (HPC) cfu/1mL
1: Analysis Start Date		---	---	03-Jul-14	03-Jul-14	03-Jul-14
2: Analysis Start Time		---	---	15:45	15:45	15:20
3: Analysis Approval Date		--	--	04-Jul-14	04-Jul-14	07-Jul-14
4: Analysis Approval Time		--	--	14:49	14:49	10:53
5: MAC		--	--	0	0	---
6: 26F9D RW RW-QMS: Raw Water 26F9D RW	02-Jul-14 08:14	17.0	---	0	0	21
7: 6712 NR DW DW1-QMS Daycare 6712 NR/DW	02-Jul-14 08:30	17.0	1.01	0	0	4
8: 1EC6A NR DW DW2-QMS Staff Room Tap 1EC6A NR/DW	02-Jul-14 08:20	17.0	1.10	0	0	1

Total and/or Free Residual Chlorine was not analyzed by SGS Environmental Services.

Carrie Greenlaw  
Project Specialist  
Environmental Services, Analytical