



SGS Canada Inc.
P.O. Box 4300 - 185 Concession St.
Lakefield - Ontario - KOL 2H0
Phone: 705-652-2000 FAX: 705-652-6365

Project : PO#017018

February-28-13

OCWA-Trent Valley (Quinte Mohawk School)

Attn : James Taylor

Date Rec. : 26 February 2013
LR Report: CA16991-FEB13

Box 20157, 131 St. Paul St.
Belleville, ON
K8N 5V1,

Copy: #1

Phone: 613-962-5454
Fax:pdf-ID Plant

CERTIFICATE OF ANALYSIS

Final Report

Sample ID	Sample Date & Temperature Time Upon Receipt °C	Free Chlorine mg/L	Total Chlorine mg/L	Coliform cfu/100mL	E. Coli cfu/100mL	Heterotrophic Plate Count (HPC) cfu/1mL
1: Analysis Start Date	---	---	---	26-Feb-13	26-Feb-13	26-Feb-13
2: Analysis Start Time	---	---	---	13:45	13:45	13:10
3: Analysis Approval Date	--	--	--	27-Feb-13	27-Feb-13	28-Feb-13
4: Analysis Approval Time	--	--	--	16:56	16:56	11:35
5: MAC	--	--	--	0	0	---
6: 6712 NR/DW QMS Daycare	25-Feb-13 12:01	8.0	1.19	0	0	0
7: IF432 NR/DW QMS Fountain Water Front Entrance	25-Feb-13 12:09	8.0	1.03	0	0	0

Total and/or Free Residual Chlorine was not analyzed by SGS Environmental Services.



Carrie Greenlaw
Project Specialist
Environmental Services, Analytical