



Not Reportable as per Chain of Custody  
Works #: 1156

Project : PO#017018

**SGS Canada Inc.**

P.O. Box 4300 - 185 Concession St.  
Lakefield - Ontario - KOL 2H0  
Phone: 705-652-2000 FAX: 705-652-6365

25-April-2014

**OCWA-Trent Valley (Quinte Mohawk School)**

Attn : James Taylor

Date Rec. : 23 April 2014

LR Report: CA17027-APR14

Box 20157, 131 St. Paul St.  
Belleville, ON  
K8N 5V1,

Copy: #1

Phone: 613-962-5454  
Fax:pdf-ID Plant

# CERTIFICATE OF ANALYSIS

## Final Report

Sample ID	Sample Date & Temperature Time Upon Receipt °C	Total Chlorine mg/L	Free Chlorine mg/L	Total Coliform cfu/100mL	E. Coli cfu/100mL	Heterotrophic Plate Count (HPC) cfu/1mL
1: Analysis Start Date	---	---	---	23-Apr-14	23-Apr-14	23-Apr-14
2: Analysis Start Time	---	---	---	13:40	13:40	13:15
3: Analysis Approval Date	--	---	--	24-Apr-14	24-Apr-14	25-Apr-14
4: Analysis Approval Time	--	---	--	14:48	14:48	10:46
5: MAC	--	---	--	0	0	---
6: 26F9D RW RW-QMS: Raw Water 26F9D RW	22-Apr-14 08:05	11.0	---	0	0	9
7: 6712 NR DW DW1-QMS Daycare 6712 NR/DW	22-Apr-14 08:20	11.0	1.67	0	0	0
8: 13481 NR/DW DW3-QMS: Fountain Water Boys Bathroom 13481 NR/DW	22-Apr-14 08:10	11.0	1.83	0	0	0

Total and/or Free Residual Chlorine was not analyzed by SGS Environmental Services.



Carrie Greenlaw  
Project Specialist  
Environmental Services, Analytical