



SGS Canada Inc.

P.O. Box 4300 - 185 Concession St.
Lakefield - Ontario - KOL 2H0
Phone: 705-652-2000 FAX: 705-652-6365

**Not Reportable as per Chain of Custody
Works #: 1156**

Project : PO#017018

21-August-2014

OCWA-Trent Valley (Quinte Mohawk School)

Attn : James Taylor

Date Rec. : 19 August 2014

LR Report: CA17820-AUG14

Box 20157, 131 St. Paul St.
Belleville, ON
K8N 5V1,

Copy: #1

Phone: 613-962-5454
Fax:pdf-ID Plant

CERTIFICATE OF ANALYSIS

Final Report

Sample ID	Sample Date & Time	Temperature Upon Receipt °C	Total Chlorine mg/L	Free Chlorine mg/L	Total Coliform cfu/100mL	E. Coli Heterotrophic cfu/100mL	Plate Count (HPC) cfu/1mL
1: Analysis Start Date		---	---	---	19-Aug-14	19-Aug-14	19-Aug-14
2: Analysis Start Time		---	---	---	12:00	12:00	11:35
3: Analysis Approval Date		--	---	--	21-Aug-14	21-Aug-14	21-Aug-14
4: Analysis Approval Time		--	---	--	10:52	10:52	10:52
5: MAC		--	---	--	0	0	---
6: 26F9D RW RW-QMS: Raw Water 26F9D RW	18-Aug-14 08:25	18.0	---	---	0	0	0
7: 6712 NR DW DW1-QMS Daycare 6712 NR/DW	18-Aug-14 08:15	18.0	1.47	1.19	0	0	4
8: 1F432 NR/DW DW3-QMS: Front Entrance Fountain 1F432 NR/DW	18-Aug-14 08:05	18.0	0.52	0.42	0	0	192

Total and/or Free Residual Chlorine was not analyzed by SGS Environmental Services.



Carrie Greenlaw
Project Specialist
Environmental Services, Analytical