

SGS Canada Inc.

P.O. Box 4300 - 185 Concession St. Lakefield - Ontario - KOL 2HO

Phone: 705-652-2000 FAX: 705-652-6365

Not Reportable as per Chain of Custody

Works #: 1156

Project: PO#017018

28-November-2013

Date Rec.: 26 November 2013 LR Report: CA18840-NOV13

Copy: #1

OCWA-Trent Valley (Quinte Mohawk School)

Attn: James Taylor

Box 20157, 131 St. Paul St. Belleville, ON K8N 5V1,

Phone: 613-962-5454 Fax:pdf-ID Plant

CERTIFICATE OF ANALYSIS Final Report

Sample ID	Sample Date & Te Time Up	emperature oon Receipt °C	Free Chlorine mg/L	Total Coliform cfu/100mL	E. Coli l cfu/100mL	Heterotrophic Plate Count (HPC) cfu/1mL
1: Analysis Start Date				26-Nov-13	26-Nov-13	26-Nov-13
2: Analysis Start Time				14:25	14:25	13:55
3: Analysis Approval Date				27-Nov-13	27-Nov-13	28-Nov-13
4: Analysis Approval Time				17:03	17:03	12:07
5: MAC				0	0	
6: 26F9D RW RW-QMS: Raw Water 26F9D RW	25-Nov-13 10:34	9.0		0	0	29
7: 6712 NR DW DW1-QMS Daycare 6712 NR/DW1	25-Nov-13 10:44	9.0	1.09	0	0	0
8: 1F432 NR/DW DW3-QMS: Fountain Water Front Entrance 1F432 NR/DW3	25-Nov-13 10:50	9.0	0.96	0	0	0

Total and/or Free Residual Chlorine was not analyzed by SGS Environmental Services.

Project Specialist

Environmental Services, Analytical