



SGS Canada Inc.

P.O. Box 4300 - 185 Concession St.
Lakefield - Ontario - K0L 2H0
Phone: 705-652-2000 FAX: 705-652-6365

Project : PO#017018

October-18-12

OCWA-Trent Valley (Quinte Mohawk School)

Attn : Steve Arnold

Date Rec. : 16 October 2012

LR Report: CA17812-OCT12

Box 20157, 131 St. Paul St.
Belleville, ON
K8N 5V1,

Copy: #1

Phone: 613-962-5454
Fax:pdf-ID Plant

CERTIFICATE OF ANALYSIS

Final Report

Sample ID	Sample Date & Time	Temperature Upon Receipt °C	Sodium mg/L
1: Analysis Start Date		---	17-Oct-12
2: Analysis Start Time		---	12:34
3: Analysis Approval Date		--	18-Oct-12
4: Analysis Approval Time		--	08:34
5: MAC		--	20*
6: AO/OG		---	200
7: MDL		---	0.01
8: 26F9D RW Raw Water	15-Oct-12 11:54	12.0	21.9

MAC - Maximum Acceptable Concentration
AO/OG - Aesthetic Objective / Operational Guideline
MDL - SGS Method Detection Limit
*Sodium > 20mg/L is an indicator of adverse water quality.


Carrie Greenlaw
Project Specialist
Environmental Services, Analytical